

The year 2002 was a very busy year for the physical property of the church building: exterior.

A List of what was done to the church proper:

Repainting where necessary (replacing the mortar between stone blocks).

Stone acid washed and a sealer put on.

Flashing was replaced (roofing replaced where needed).

-- Some of the smaller roofs were redone to meet code requirements.

+ Window frames repaired and sealed.

+ Chimney interior was rebuilt and a stainless steel liner was installed.

+ Bell cradle was refurbished.

New screening was installed in the belfry (no more bats in our belfry - or pigeons or other flying objects).

+ New double paned window installed at the foot of the stairs (replaces single paned window, and it does feel warmer in there).

+ Outside basement door block work repaired and raised (lots of water was entering the basement).

+ A french drain was also installed near the basement door (it was a low spot on the grounds).

From 2002 Budget Report Line 8020 the total cost for our Capital Improvements on our church building totalled, \$143,642.50. If you need further information concerning the project and/or cost, please speak to Gene Weisbrod, Marshall Dawsey or Maureen.